

KIT 5
THROWS

Instructions for KIT 5

SET-UP AND OPERATION OF EDM
(Electromagnetic Distance Measurement)

Throws

Preliminaries: Ensure all batteries are put on charge well before the meeting.

1. For Long Throws

a) Location: Must give a clear view of the landing sector, circle centre and rim (or 8m point and arc for javelin).

b) Assembly and Levelling:

- i. Ensure tripod is set firmly into the ground at a convenient working height for all users with top plate as level as possible (use spirit level).
- ii. Fit tribrach, making sure securing screw is tight and base cannot move.
- iii. Level Tribrach, use two foot screws to centre bubble between them then adjust remaining screw to centre bubble in bubble-level.
- iv. Fit geodimeter on tribrach (power socket goes in recess), lock tribrach in place.
- v. Adjust for parallax - hand in front of telescope and check hairlines are sharp, adjust lens as necessary.
- vi. Connect external batteries or mains power source (if used).

TO POWER SOCKET ON TRIBRACH, NOT KEYPAD.

c) Setting up the Instrument:

- i. Turn power on.
- ii. Either press **YES (enter)** to continue if already set up or **NO (←)** for machine to go to set up.
- iii. Check level on display - if necessary carefully adjust on tribrach foot screws to centre both index marks [*Prolonged adjustment will force return to c) i.*], and press **ENTER (Yes)**.
- iv. Machine will perform self checks and rotate around then rotate back again.

IF NECESSARY →

Note:

- v. Enter approx. temperature, press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).
- vi. Enter approx. atmospheric pressure, press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).
- vii. Enter prism constant **Offset = 0.00**, press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).
- viii. Enter **HA ref = 00.00.00**, press **ENTER (Yes)**.

SHOWS:
FSTD P0 XX:XX
HA XX:XX:XX
VA XX:XX:XX

Job No = 1 Press 'Yes'

IF
NECESSARY

- ix. Press **PRG 60**
- x. Instrument reads: **IMEM**
 EXMEM
 SERIAL
- xi. Ignore, press **ENTER (Yes)**.
- xii. Prism in centre of circle (or 8m point), focus on prism, press **A/M**.
- xiii. Wait for measurement (approx. **3** sec.), press **REG**.
- xiv. User = '0', press back space '**←**', enter circle radius (**1.25** for discus, **1.0675** for hammer/shot, **8.0** for javelin), press **ENTER (Yes)**.
- xv. User = (blank), enter '**1**', press **ENTER (Yes)**. (this is round number)
- xvi. User = (blank), enter User No. '**1**', press **ENTER (Yes)**. (this is entrant number)
- xvii. Place prism on inner edge of circle or arc, focus on prism, press **A/M**.
- xviii. Wait for measurement (approx. **3** sec.), press **REG**. Record this measurement (should read '**0**').
- xix. To get back to next measurement press **No** to store.
- xx. Take two initial check measurements at different locations in, or adjacent to, throwing area. Checks should be marked and measured using a steel tape. Record all readings and measurements. Repeat checks and edge of circle or arc at end of competition.

d) Taking Measurements:

- i. Enter Round No. '**1**', press **ENTER (Yes)**.
- ii. Enter User No. '**1**', press **ENTER (Yes)**.
- iii. Aim telescope at landing point, focus on target prism when positioned. When cross hairs locked on prism, press **A/M**.
- iv. Wait for measurement (approx. 6 sec.), press **REG**.
- v. Record distance measured and signal clearly to prism handler to remove prism (*this may be done as soon as you are sure reading is correct*).
- vi. Display shows 'Store?', press '**NO**'.
- vii. Return to d) i. and repeat for all further trials.

GENERIC EDM VERTICAL JUMPS

SET-UP AND OPERATION OF EDM
(Electromagnetic Distance Measurement)

Vertical Jumps

- i. **Preliminaries:** Ensure all batteries are put on charge well before the meeting.

2. For High Jump and Pole Vault

- a) **Location:** Must give a clear and complete view of the bar. For Pole Vault centre of runway is best, and high jump centre behind fan.

b) Assembly and Levelling:

- i. Ensure tripod is set firmly into the ground at a convenient working height for all users with top plate as level as possible (use spirit level).
- ii. Fit tribrach, making sure securing screw is tight and base cannot move.
- iii. Level Tribrach, use two foot screws to centre bubble between them then adjust remaining screw to centre bubble in bubble-level.
- iv. Fit geodimeter on tribrach (power socket goes in recess), lock tribrach in place.
- v. Disinfect eyepiece and surrounds to minimise possibility of eye infections.
- vi. Adjust for parallax - hand in front of telescope and check hairlines are sharp, adjust lens as necessary.
- vii. Connect external batteries or mains power source (if used).

c) Setting up the Instrument:

- i. Turn power on.
- ii. Either press **YES (enter)** to continue or **NO (←)** for machine to go straight to next step.
- iii. Check level on display - if necessary carefully adjust on tribrach foot screws to centre both index marks [*Prolonged adjustment will force return to c) i.*], and press **ENTER (Yes)**.
- iv. Screen will instruct to turn instrument through 200 grads (180°), do so and when display shows 'A/M', press **A/M**.
- v. Wait for completion of internal check and rotate instrument through 200grads (180°) again.

Note: servo assisted instrument will perform items iv. & v itself automatically.

- vi. Enter approx. temperature, press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).
- vii. Enter approx. atmospheric pressure, press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).
- viii. Enter prism constant (Zero for our prisms), press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).

Note: some instruments may skip from item v. to ix. Missing out vi., vii. & viii..

- ix. Enter horizontal component (00.00.00), press **ENTER (Yes)**.
- x. Press **PRG 0**, then enter.
- xi. Enter approx. temperature, press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).
- xii. Enter approx. atmospheric pressure, press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).
- xiii. Enter prism constant (Zero for our prisms), press **ENTER (Yes)** (*it may be necessary to press 'ENTER' twice*).
- xiv. **Note:** some instruments may skip from item v. to ix. Missing out x., xi. & xii..
- xv. Enter horizontal component (00.00.00), press **ENTER (Yes)**.
- xvi. Set prism at the back of the box for pole vault, or on the ground under the centre of the bar for high jump.
- xvii. Sight on the prism, take the measurement by pressing **A/M**.
- xviii. **Leave the instrument locked in position and only vertical direction from now on.**
- xix. Press Enter key until screen shows HA:,HD:,VD:.
- xx. Sight on the ground, back of the box or under the middle of the high jump to set the zero height.
- xxi. Press **MNU** key, Then Press 1 **SET**, Then Press 2 **PRESET**, Then Press 2 **ROE**.
- xxii. Enter **ROE** of 0.000 and press **ENTER**.
- xxiii. To check the height sight on the top of the bar vertically above the point on the ground. Do not attempt any adjustments of the instrument in a horizontal direction and do not attempt to take any measurements.
- xxiv. Use the **VD** reading as height measurement.

5

SET-UP AND OPERATION OF EDM
(Electromagnetic Distance Measurement)

GENERIC
EDM
HORIZ
JUMPS

Horizontal Jumps

Preliminaries: Ensure all batteries are put on charge well before the meeting.

2. For Long and Triple Jump

a) **Location:** Must give a clear and complete view of the landing sand pit and take off board.

b) **Assembly and Levelling:**

- i. Ensure tripod is set firmly into the ground at a convenient working height for all users with top plate as level as possible (use spirit level).
- ii. Fit tribrach, making sure securing screw is tight and base cannot move.
- iii. Level Tribrach, use two foot screws to centre bubble between them then adjust remaining screw to centre bubble in bubble-level.
- iv. Fit geodimeter on tribrach (power socket goes in recess), lock tribrach in place.
- v. Disinfect eyepiece and surrounds to minimise possibility of eye infections.
- vi. Adjust for parallax - hand in front of telescope and check hairlines are sharp, adjust lens as necessary.
- vii. Connect external batteries or mains power source (if used).

c) **Setting up the Instrument:**

- i. Turn power on.
- ii. Either press **YES (enter)** to continue or **NO (←)** for machine to go straight to next step.
- iii. Check level on display - if necessary carefully adjust on tribrach foot screws to centre both index marks [*Prolonged adjustment will force return to c) i.*], and press **ENTER(Yes)**.
- iv. Screen will instruct to turn instrument through 200 grads (180°), do so and when display shows 'A/M', press **A/M**.
- v. Wait for completion of internal check and rotate instrument through 200 grads (180°) again.

Note: servo assisted instrument will perform items iv. & v itself automatically.

- vi. Enter approx. temperature, press **ENTER(Yes)** (*it may be necessary to press 'ENTER' twice*).
- vii. Enter approx. atmospheric pressure, press **ENTER(Yes)** (*it may be necessary to press 'ENTER' twice*).
- viii. Enter prism constant (Zero for our prisms), press **ENTER(Yes)** (*it may be necessary to press 'ENTER' twice*).

Note: some instruments may skip from item v. to ix. Missing out vi., vii. & viii..

- 6
- ix. Enter horizontal component (00.00.00), press **ENTER(Yes)**.
 - x. Press the program button **PRG**
 - xi. Enter '24', press **ENTER(Yes)** (*this is the horizontal jumps program, throws program is '60', vertical jumps is '0' menu 1.2.2*).
 - xii. Enter Job No. '1', press **ENTER(Yes)**. Instrument reads: **IMEM**
EXMEM
SERIAL
 - xiii. Ignore, press **ENTER(Yes)**.
 - xiv. Screen shows : **1 Known Line**
 2. Unknown Line
 - xv. **Select 2**
 - xvi. Screen shows **STN = 1** - press **YES**
 - xvii. Screen shows **HT measure?** - press **YES**
 - xviii. Screen shows **Ih = 0** - press **YES**
 - xix. Screen shows Ref. line point A
 Pno = 1 - press **YES**
 - xx. Screen shows **SH = 0.000** - press **YES**
 - xxi. Screen shows **STD**
 HA
 VA
 - xxii. Focus on prism on one end of take off board - Press **A/M**
 - xxiii. Instrument shows "measuring", when finished - Press **Reg**
 - xxiv. Screen shows Ref. line point B
 Pno = 2 - press **YES**
 - xxv. Screen shows **SH = 0.000** - press **YES**
 - xxvii. Screen shows **STD**
 HA
 VA
 - xxviii. Focus on prism on other end of take off board - Press **A/M**
 - xxix. Instrument shows "measuring", when finished - Press **Reg**
 - xxx. Screen shows **1. Measure**
 2. Setout
 3. [...] - Select **1**

- xxxi. Screen shows **Slope = xx.xxxx** - Press YES
- xxxii. Screen shows **SH = 0.000** - Press YES
- xxxiii. Screen shows **STD**
HA
VA

Set-up is finished.

d) Taking Measurements.

- i. For a measurement, focus on the prism.
- ii. Press A/M
- iii. Screen shows ?????????? =
 ?????????? =
 RT of s =
 ?????????? =
- iv. **Read RT of s** - This is the distance and may show as negative.
- iv. For the next jump just focus on the prism and press A/M again and so on.
- v. Immediately before and after the competition, confirm the instrument accuracy on two pre-measured check marks at either end of the pit and at the centre of the take-off board (this last one should of course read zero)
- vi. Helpful hint:- Refocus on the centre of the pit between jumps to minimise change when measuring.